

Infrared Survey Report



**Home of:
Mr. and Mrs. Sample Client
926 Main Street
Your Town, USA 12345**

Prepared by:
**Qualified Contractor
Your Town, USA
info@EnergyScanIR.com
Toll-Free 888-SCAN 4 IR
(888-722-6447)**

www.EnergyScanIR.com



December 12, 2008

Mr. and Mrs. Sample Client
926 Main Street
Your Town, USA 12345

Dear Mr. & Mrs. Client:

Please find below, the report from the infrared (IR) survey of heat loss that was conducted today.

This report is designed to be clear, easy to understand and helpful. If there is anything you would like for us to explain, or if there is other information you would like, please feel free to call me at 888-722-6447.

We thank you for the opportunity to be of service to you.

Sincerely,

Peter Hopkins
Authorized EnergyScanIR® Contractor
Certified Infrared Thermographer

Survey Information

Survey Report #:	PH-121208-2
Survey date:	12-12-08
Thermographer:	Peter Hopkins
Weather:	Sunny
Outdoor temperature:	45 °F
Indoor temperature:	75 °F
Temp diff In-Out (Δt):	30 F °

Please contact us with any questions or comments.
info@EnergyScanIR.com www.EnergyScanIR.com Toll-Free 888 SCAN 4 IR



Your EnergyScanIR® Survey

General

This survey report reflects the conditions of the property at the time of the survey. Hidden or concealed defects cannot be included in this report, therefore no warranty is either expressed or implied, however an earnest effort was made to discover defects.

Understanding Infrared Thermography

Infrared imagery is often a grayscale picture whose scales (or shades of gray) represent the differences in temperature and emissivity of objects in the image. As a general rule, objects in the image that are lighter in color are warmer and darker objects are cooler. No object in the IR images attached is detected via visible light wavelengths (400-700 nanometers) rather, only from infrared wavelengths of 3000-14000 nanometers. Lights and other relatively hot objects are very evident, but as a result of their heat, not light emissions.

When an image is taken by our infrared camera, it is recorded on the internal memory of the camera and later converted to a digital image file with the help of a computer. The image may be then modified in a number of ways to enhance its value to the end user. In the case of this report, the images were digitized and then adjusted for contrast and brightness before being scaled and placed into our custom program and later converted to this PDF file.

Survey Analysis

We were contracted to find areas of wasted energy. Given the time frame, this survey of your home was focused on the heat loss, by finding insulation that is missing, misplaced or damaged in the exterior walls and ceilings and by finding air leakage by reducing the internal pressure with the blower door.

Every attempt was made to image the home according to the ASTM-C1060 Standard, however, due to circumstances beyond our control, this might not have been possible. For example, because of inaccessible areas, such as areas behind furniture or an appliance that covers a wall, ceiling or floor, we may not have been able to obtain 100% coverage of all inside surfaces.

Please contact us with any questions or comments.

info@EnergyScanIR.com www.EnergyScanIR.com Toll-Free 888 SCAN 4 IR



Recommendations

We recommend all areas showing anomalies be tested to find out the cause (s) and when warranted, these areas should be repaired. Our recommendations are not intended as criticisms of the building - but rather as professional opinions regarding the conditions that we found.

We are often asked how to prioritize the anomalies that have been identified in our reports. Below, find the three categories:

- Conditions which affect performance and life safety issues (if any) are of course, of the highest priority. (These will be show with an astericks.)
- Next are conditions that do not appear to pose any threat to the safety of the occupants of the building, but that need repair because they create a condition that affects the performance of the building or could deteriorate the building itself. Examples would be items that appear to be large areas of heat loss or air infiltration. These areas should be tested by a qualified repairman to determine the appropriate corrective action.
- Finally, lower priority conditions that have a low impact on performance of the thermal, air and/or moisture barriers, but have reached the level of a reportable anomaly. These should be evaluated to determine if it is cost-effective to conduct repairs.

Building Orientation in this Report

We will describe the locations of the various features of this property, left or right, etc., as though we were standing in street looking at the front of building and/or give the room that you gave us.

Information Contained On the Thermographic Report Pages

Through the use of thermal imaging, we have found areas with anomalies. These anomalies have been notated on the individual thermographic reports that follow (typically, two per page). Infrared thermographs and visual photographs were taken during survey. If we did not find a reportable anomaly, we did not create an individual thermographic report.


Please contact us with any questions or comments.
info@EnergyScanIR.com www.EnergyScanIR.com Toll-Free 888 SCAN 4 IR

Interpretation

When viewing IR images, anomalies commonly present where the conditions exist and/or where our reference (arrows or area boxes) are located. When IR images are taken during colder months (winter), the areas of deficient insulation look darker. When IR images are taken during warmer months (summer), the areas of deficient insulation look lighter.


SUMMER

Infrared Image shows warm areas that are missing insulation.



WINTER


Infrared Image shows cool areas (purple) that are missing insulation.




Please contact us with any questions or comments.

info@EnergyScanIR.com www.EnergyScanIR.com Toll-Free 888 SCAN 4 IR

Thermographic Report Pages below...


	
<p>Date 12/12/2008</p>	<p>Image.File name IR_0639.jpg</p>
<p>Location: Entry Area Where: Ceiling Condition: Appears to be missing or loose insulation Recommendation: We recommend further investigation of this area and repair as needed.</p> <p>CORRECTED BY: _____ DATE ____-____-_____</p>	


	
<p>Date 12/12/2008</p>	<p>Image.File name IR_0641.jpg</p>
<p>Location: Entry Area Where: Right wall Condition: Appears to be missing or loose insulation Recommendation: We recommend further investigation of this area and repair as needed.</p> <p>CORRECTED BY: _____ DATE ____-____-_____</p>	

	
<p>Date 12/12/2008</p>	<p>Image.File name IR_0672.jpg</p>
<p>Location: Guest Bedroom 2 Where: Left wall Condition: Appears to be missing or loose insulation Recommendation: We recommend further investigation of this area and repair as needed.</p> <p>CORRECTED BY: _____ DATE ____-____-____</p>	

	
<p>Date 12/12/2008</p>	<p>Image.File name IR_0645.jpg</p>
<p>Location: Entry Area Where: Exterior door Condition: Weatherstripping at exterior door(s) appears to have air infiltration due to gaps or missing sections. Recommendation: We recommend further investigation of this area and repair as needed.</p> <p>CORRECTED BY: _____ DATE ____-____-____</p>	

Please contact us with any questions or comments.
 info@EnergyScanIR.com www.EnergyScanIR.com Toll-Free 888 SCAN 4 IR

	
<p>Date 12/12/2008</p>	<p>Image.File name IR_0653.jpg</p>
<p>Location: Master Bedroom Where: Ceiling Condition: Appears to be missing or loose insulation Recommendation: We recommend further investigation of this area and repair as needed.</p> <p>CORRECTED BY: _____ DATE ____-____-____</p>	

	
<p>Date 12/12/2008</p>	<p>Image.File name IR_0655.jpg</p>
<p>Location: Master Bedroom Where: Ceiling Condition: Appears to be missing or loose insulation Recommendation: We recommend further investigation of this area and repair as needed.</p> <p>CORRECTED BY: _____ DATE ____-____-____</p>	